



## HOME INSPECTION REPORT

1234 Main St. Minneapolis MN 55407

Buyer Name 09/24/2020 9:00AM



Inspector
George Ury
ASHI Certified Inspector
952.334.7980
george@structuretech.com



Agent Name 555-555-5555 agent@spectora.com

# TABLE OF CONTENTS

1: Overview	5
2: Roof Covering	6
3: Exterior	7
4: Siding	10
5: Basement / Foundation / Structure	12
6: Plumbing	13
7: Electrical	15
8: Heating	17
9: Cooling	19
10: Interior	20
11: Attic	22
12: Garage	24
13: Environmental	25
Standard of Practice	26

The service recommendations in this report should be completed by licensed, qualified, competent specialists. These specialists may identify additional defects or recommend upgrades that could affect your valuation of the property. This inspection was conducted in accordance with the ASHI Standard of Practice.

This report is the exclusive property of Structure Tech Home Inspections and the Client whose name appears within, and its use by any unauthorized persons is prohibited.

## **Observation Key**

Maintenance & Information - Components that require routine maintenance or service as part of homeownership. This section may also include observations that do not necessarily require service but were worth noting in the report. Items related to energy efficiency and improved home performance are also listed under this section.



**Attention Recommended** - Service, maintenance, repair, or replacement is recommended. Recommendations for added safety and further inspection by qualified professionals are also included in this section.

Critical/Important - Unsafe or non-functional components that should be serviced as soon as possible, and items at or near the end of their service life that would affect the functionality of the building (e.g. roofing, HVAC, water heaters, foundations, galvanized steel water pipes).

Items or systems not specifically noted in this report were considered acceptable or functioning at the time of inspection as per the ASHI Standard of Practice. Items and systems that were inspected are noted on the STANDARDS tab.

## **SUMMARY**

- 2.1.1 Roof Covering Sloped Roof: Roof covering in acceptable condition
- 3.9.1 Exterior Downspouts: Short extensions

- 3.14.1 Exterior Vent Terminals: Dryer maintenance reminder
- 3.15.1 Exterior Combustion Air Intake: Remember to clean
- 3.16.1 Exterior Air Exchanger Intake/Exhaust: Dirty intake
- 3.18.1 Exterior Exterior Faucets: Vacuum breakers
- 3.18.2 Exterior Exterior Faucets: Winterization reminder
- 4.4.1 Siding Stucco: Intrusive moisture testing
- 5.5.1 Basement / Foundation / Structure Sump System: No pump
- 5.5.2 Basement / Foundation / Structure Sump System: Cover not airtight
- 6.13.1 Plumbing Toilets: Toilet fill valves lack air gap
- 6.14.1 Plumbing Bathtubs & Showers: Bathtub faucet below spill line
- 6.14.2 Plumbing Bathtubs & Showers: Hot & cold reversed single handle
- 6.14.3 Plumbing Bathtubs & Showers: Tub spout loose
- 7.1.1 Electrical Main Panel: Main electrical panel acceptable
- 7.2.1 Electrical Interior Panel Components: Excess sheathing
- 7.3.1 Electrical Service Grounding & Bonding: Water softener
- 7.6.1 Electrical Exterior Lights & Outlets: Weatherproof cover missing at outlet
- 8.2.1 Heating Operation/Condition: Heating system operational
- 8.9.1 Heating Air Exchange System (HRV): HRV not balanced
- ▲ 8.9.2 Heating Air Exchange System (HRV): HRV not functional
- 8.13.1 Heating Humidifier: Use with caution
- 9.1.1 Cooling Operation/Condition: Cooling system operational
- 9.3.1 Cooling Compressor/Condenser: Dirty
- 2 10.5.1 Interior Windows: Condensation staining
- 2 10.9.1 Interior Fireplaces Gas: White haze
- 11.1.1 Attic Attic Access: Poorly insulated, no weatherstripping
- 2 13.1.1 Environmental Radon: Radon test in progress

# 1: OVERVIEW

## **Information**

**Style of Building** 

Single Family

**Year Built** 

2002

**Present at Inspection** 

Buyer(s)

**Type of Construction** 

Wood Frame

Weather

Clear

Occupied

Yes

**Temperature** 

80° - 85°

# 2: ROOF COVERING

## **Information**

**Roofing Material** 

**Architectural Shingles** 

### **Inspection Method**

Ladder at eaves - too steep to be safely walked

## **Observations**

2.1.1 Sloped Roof

# **ROOF COVERING IN**

**ACCEPTABLE CONDITION** 

The roof covering was in acceptable condition.





## 3: EXTERIOR


### **Observations**

3.9.1 Downspouts

### SHORT EXTENSIONS



One or more downspouts lacked proper extensions to carry the water away from the foundation. Downspouts dumping water against the building will concentrate water and greatly increase the potential for basement water problems and foundation problems. Add solid aluminum downspout extensions to carry the water at least 6 feet away from the house and beyond any landscape edging.







3.9.2 Downspouts

### DAMAGED EXTENSIONS



Maintenance & Information

One or more downspout extensions were damaged and should be replaced.



3.9.3 Downspouts

### **CONNECTED TO YARD DRAINS**

yard drains. If the yard drains filled with ice, water could back up into the downspouts and cause damage to the building. To help prevent this, install drain receptors for the yard drains and have the downspouts stop an inch or two short of the receptors. For more information on this topic, click here: Don't Connect Downspouts Directly to Yard Drains.

One or more of the downspouts drained directly into underground



3.14.1 Vent Terminals

### **DRYER - MAINTENANCE REMINDER**



Excessive lint accumulation around the dryer vent exhaust cover can cause the damper to stick open from lint. This can be a potential fire hazard and will also allow for air leakage and pest intrusion. The exhaust vent was fairly clean at the time of inspection, however have the dryer duct and terminal cleaned yearly or as needed. For more information on this topic, click here: Keeping your clothes dryer safe

3.15.1 Combustion Air Intake

# Maintenance & Information

### **REMEMBER TO CLEAN**

The combustion air intake should be checked regularly and cleared if necessary to ensure sufficient combustion air is brought into the house for fuel-burning appliances. The intake was clean at the time of inspection. For more information on this topic, click here: Combustion Air Ducts, Part II: Problems and Solutions



3.16.1 Air Exchanger Intake/Exhaust



### **DIRTY INTAKE**

The intake vent for the air exchanger was dirty and should be cleaned. This will allow proper airflow and operation of the air exchanger.




3.18.1 Exterior Faucets

### **VACUUM BREAKERS**



There were no backflow prevention devices (vacuum breakers) at one or more of the exterior faucets. These are required to protect the drinking water supply from contamination. Add vacuum breakers such as the one pictured below at the exterior faucets. For more information on this topic, click here: Why Do I Need A Vacuum Breaker?











3.18.2 Exterior Faucets

### WINTERIZATION REMINDER



Winterize all exterior faucets every fall to help prevent freeze damage. For instructions, click here: How to prevent your outside faucets from freezing

# 4: SIDING

## **Information**

## **Siding Material**

Vinyl, Brick Veneer, Stucco


## **Observations**

4.4.1 Stucco

### **INTRUSIVE MOISTURE TESTING**



Stucco siding on a house of this age is prone to water intrusion and water damage inside the walls. The stucco lacked proper gaps at the flashing and roof to allow moisture to drain. The stucco was also cracked in areas. Have intrusive moisture testing performed by a company that specializes in this. For more information on this topic, click here: Stucco Homes



# 5: BASEMENT / FOUNDATION / STRUCTURE

### **Information**

#### **Roof Structure**

Factory built truss system

### **Foundation**

Concrete block

#### **Wall Structure**

Wood Studs

### **Basement Insulation**

Foundation walls: fiberglass batts, Rim space: rigid foam

#### Floor Structure

Open web floor trusses

### **Crawl Space**

No crawl space present

### **Observations**

5.5.1 Sump System

### **NO PUMP**

There was no pump installed in the sump system, and the sump basket was dry.



5.5.2 Sump System

### **COVER NOT AIRTIGHT**

The sump basket cover was not airtight. This can allow air with relatively high levels of moisture to enter the home and can contribute to radon gas entry. Have the sump basket cover made airtight.



# 6: PLUMBING

### **Information**

**Water Distribution Pipes** 

Copper

**Water Heater Age** 

3 - 4 years old

**Main Sewer Cleanout Location** 

Base of main sewer stack

**Drain Waste & Vent Pipes** 

PVC

**Main Water Shut-Off Location** 

Basement

**Water Heater Type** 

Gas - storage tank

**Main Gas Shut-Off Location** 

Maintenance & Information

Next to furnace

### **Observations**

6.8.1 Dryer Duct

### **REMINDER TO CLEAN**


Have the dryer duct cleaned once or twice a year to help prevent lint build-up, which can lead to a fire.


6.13.1 Toilets

### TOILET FILL VALVES LACK AIR GAP



One or more of the toilet fill valves were improperly installed. An air gap is required between the CL (critical level) on the fill valve and the overflow tube. This helps prevent cross-contamination of the drinking water. Have this corrected. For more information on this topic, click here: Cross Connections at Toilets








6.14.1 Bathtubs & Showers

### **BATHTUB FAUCET BELOW SPILL LINE**



The bathtub faucet was located below the spill line of the tub, which could allow water in the tub to contaminate the drinking water supply. Have this corrected. For more information on this topic, click here: Bath Tub Faucets





6.14.2 Bathtubs & Showers

# HOT & COLD REVERSED - SINGLE HANDLE



The tub/shower valve was improperly installed. The water was hot when turned on and became cooler as the valve was turned counterclockwise. The water should be cold when the valve is turned on, and get hot as it's turned counter-clockwise. Have the valve installation corrected.




6.14.3 Bathtubs & Showers

### **TUB SPOUT LOOSE**



The tub spout athe whirlpool tub was loose and should be secured.



# 7: ELECTRICAL

## **Information**

**Service Amperage** 

200 amp

Predominant Branch Circuit Wiring

Non-metallic sheathed cable (Romex)

**Location of Main Disconnect** 

Garage

**Main Panel Type** 

Circuit Breaker

**Location of Sub Panels** 

None

### **Observations**

7.1.1 Main Panel

# MAIN ELECTRICAL PANEL ACCEPTABLE

Maintenance & Information

The main electrical panel and its interior components were in acceptable condition.




7.2.1 Interior Panel Components

### **EXCESS SHEATHING**



There was excess sheathing on one or more wires in the panel. Sheathing should not project more than 1" inside the panel box, so as not to crowd the panel.








7.3.1 Service Grounding & Bonding

# Attention Recommended

### WATER SOFTENER

The water distribution piping was no longer bonded because the bypass valve at the water softener is plastic. Add a grounding strap to connect the water piping going in and out of the water softener. For more information on this topic, click here: Water Softener Installation Defects







7.6.1 Exterior Lights & Outlets

# WEATHERPROOF COVER MISSING AT OUTLET



One or more exterior outlets were missing a weatherproof cover, which should be replaced to help prevent damage to the outlets. Today's standards require weatherproof covers that allow a cord to be plugged in while the cover is in the closed position.



# 8: HEATING

### **Information**


**Heating System**Forced Air

**Heating System Age** 

17 - 18 years old

### Air Exchange System (HRV): HRV (Heat Recovery Ventilator)

An HRV (heat recovery ventilator) was installed as the home's air exchange system. Follow the manufacturer's recommendations for operation and cleaning. For general operation and maintenance information, click here: HRV, Part 2 of 3: Maintenance & Operation



### **Observations**

8.2.1 Operation/Condition

# HEATING SYSTEM OPERATIONAL



The heating system responded properly to the thermostat controls and had a low level of carbon monoxide in the flue gas. Have the heating system serviced and inspected annually. For more information, and reasons we recommend annual inspections of heating systems, click here: Are annual furnace inspections really necessary?



8.9.1 Air Exchange System (HRV)



### **HRV NOT BALANCED**

The heat recovery ventilator was not balanced. This can create either negative or positive pressure in the house, which is not energy efficient. Have the system properly balanced. For more information on this topic, click here: HRVs, Part 3 of 3: Installation Defects



8.9.2 Air Exchange System (HRV)

### **HRV NOT FUNCTIONAL**



The heat recovery ventilator (HRV) was not functional. Have the unit repaired or replaced. The home could experience moisture and indoor air quality issues without the HRV running during the winter.





fan motor seized

8.13.1 Humidifier

### **USE WITH CAUTION**



Humidifiers are not tested for operation. Use with caution as they can cause moisture problems in the home. For more information on this topic, click here: Whole-House Humidifiers Harm Houses



# 9: COOLING

### **Information**

**Cooling Method**Forced Air

**Refrigerant Type** R-22 Cooling System Age 17 - 18 years old

### **Observations**

9.1.1 Operation/Condition

### **COOLING SYSTEM OPERATIONAL**




The air-conditioning responded to thermostatic controls and achieved an acceptable differential temperature split between the supply and return air (approximately 15-20 degrees).

### 9.3.1 Compressor/Condenser

### **DIRTY**



The condensing coil was dirty, which will reduce the efficiency of the unit. Have the coil cleaned. For more information on this topic, click here: Three Simple AC Maintenance Items.





# 10: INTERIOR

# Information

Fireplace Type

Gas fireplace(s)

## **Limitations**

Styles & Materials

### **INTERIOR LIMITATIONS**

Occupied


## **Observations**

10.5.1 Windows

### **CONDENSATION STAINING**



There was condensation staining on a number of windows. Excess moisture in the air during winter can condense on the cold surfaces of the glass. When the water drips off, it can leave mold or mildew staining, as well as remove the protective varnish or paint. The best way to prevent this is to lower the indoor humidity levels and keep the windows open to the interior (no window coverings). For more information on this topic, click here: Controlling Window Condensation









10.9.1 Fireplaces - Gas

### WHITE HAZE



There was a white haze on the glass at the gas fireplace. This is cosmetic and can be cleaned. For more information on this topic, click here: Dirty glass at gas fireplaces



# 11: ATTIC

## **Information**

**Attic Inspection Method**Entered attic

**Attic Insulation**Loose fill fiberglass

**Vapor Barrier**Polyethylene

Attic Insulation: Attic insulation and roof framing acceptable

The attic insulation and roof frame were in acceptable condition.










## **Observations**

11.1.1 Attic Access



### POORLY INSULATED, NO WEATHERSTRIPPING

The attic access panel was covered with a piece of fiberglass insulation. It can be difficult to get the fiberglass to drop back down on top of the attic access panel if it is not properly attached. Insulate the top of the access panel with rigid foam. Additionally, the access panel did not make a tight seal at the ceiling. Have the access weatherstripped to help prevent air leakage at this location. For more information on this topic, click here: Poorly insulated attic access panels







# 12: GARAGE

### **Information**

### **Garage Doors: Garage door testing**

Garage door openers should be tested for auto-reverse monthly. This test should be conducted with a 2x4 lying flat on the ground, and allowing the door to close on the 2x4. If the door does not reverse, it should be adjusted or replaced to prevent a child or animal from getting trapped beneath it. Be advised, however, that testing this safety feature may result in damage to the door, opener, or both, which is why this test is not conducted at the time of inspection. For a short video showing how this test is performed, click here: How To Do a Garage Door Safety Test

# 13: ENVIRONMENTAL

### **Observations**

13.1.1 Radon

# Maintenance & Information

### **RADON TEST IN PROGRESS**

A short-term (48 hour) radon test was being performed at the same time as the home inspection. The results of that test are sent in a separate report. For more information about radon and radon testing, click here: Radon Testing - What the Results Mean

# STANDARDS OF PRACTICE

#### **Roof Covering**

The inspection of the roof includes the roofing materials, roof drainage systems, flashings, skylights, chimneys, and roof penetrations.

#### **Exterior**

The inspection of the exterior includes the siding, flashing, trim, all exterior doors, decks, balconies, stoops, steps, porches, and guardrails. It includes eaves, soffits, and fascias that are accessible from the ground level. This also includes vegetation, grading, surface drainage, and retaining walls that are likely to adversely affect the building. This also includes adjacent entryway walkways, patios, and driveways.

#### Siding

The inspection of the siding includes the installation and condition of the exterior cladding, flashing, and trim.

#### **Basement / Foundation / Structure**

The inspection of the structural components includes the foundation and framing.

#### **Plumbing**

The inspection of the plumbing system includes the following: the water supply and distribution system, including all fixtures and faucets; the drain, waste and vent systems, including all fixtures; the water heating equipment and hot water supply system; vent systems, flues, and chimneys; fuel storage and fuel distribution systems; drainage sumps, sump pumps, and related piping. We do not operate any shut-off valves.

For the clothes washer and dryer, we perform only a cursory test for the basic operation of the appliances. For example, we make sure the dryer turns on with normal controls and the tumbler is turning. We do not check the accuracy of the dryer thermostat, moisture sensor, or timers, nor do we perform any testing on similar features.

#### **Electrical**

The inspection of the electrical system includes the following: the service drop; the service entrance conductors, cables, and raceways; service equipment and main disconnects; service grounding; interior components of service panels and sub panels; conductors; overcurrent protection devices; a representative number of installed lighting fixtures, switches, and receptacles; ground fault circuit interrupters and arc fault circuit interrupters.

#### Heating

The inspection of the heating system includes any installed heating equipment and their filters, vent systems, flues, and chimneys. Any readily openable access panels are also opened.

#### Cooling

The inspection of the air conditioning consists of the central and through-wall equipment (but not window units), as well as the distribution systems. Any readily openable access panels are also opened.

#### Interior

The inspection of the interior includes the following: walls, ceilings, and floors; steps, stairways, and railings; countertops and a representative number of installed cabinets; a representative number of doors and windows. Installed ovens, ranges, surface cooking appliances, microwave ovens, dishwashing machines, and food waste grinders are inspected by using normal operating controls to activate the primary function.

#### Attic

The inspection of the attic(s) includes the insulation, ventilation, and vapor retarders where visible. The inspection also includes mechanical exhaust systems (e.g. kitchen, bathrooms, laundry, clothes dryer).

#### Garage

The inspection of the garage includes the garage doors and garage door operators.

#### **Environmental**

Environmental items included in this section are specifically excluded by our standards of practice as well as our inspection agreement, but may be noted here as a courtesy, or as a convenience if additional testing was conducted at the same time as the home inspection.